




GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
May 9, 2013

Reviewed: 

Mine Name: Number 1 Clark Mine/Emeride	Permit Number: S/015/0074
Operator Name: Robert L. Clark	Inspection Date: May 8, 2013
Inspector(s): Wayne Western	Time:
Other Participants:	Mine Status: INA
Weather Condition: cool with overcast skies	Last Inspection: August 29, 2009
Bond Renewal Date: December 4, 2015	Bond Amount: \$11,900.00
Surface Ownership: SITLA	Mineral Ownership: SITLA
Last Year of Production: last annual report was for 2011	Acreage: 1.9 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The mine is listed as inactive but the annual report indicate that product has occurred from 2009 to 2011 and there was production during the inspection.

No annual report was submitted for 2012.

Annual fees were paid in 2013.

Inspection Date: May 8, 2013

Page 2 of 4

S/015/0074

The site does have step highwalls which will be reclaimed during reclamation.

The site is small and there are no structures on site.


Conclusions and Recommendations:

The Division should continue to monitor the site annually. The Permittee should submit an annual report for 2012.

Directions to Site:

The site is located next to the old Cowboy Mine which is shown on the 7.5 minute quad.

Inspector's Signature



WHW:


cc: (OPERATOR)

John Blake, SITLA

O:\M015-Emery\S0150074-Cowboy-Emeride-BobClark\inspections\Insp-05082013.doc



Truck being loaded with product.



Pickup truck used to support operations.



Overburden material



Overburden material and highwall.